

HABS
DC,
WASH.
220-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum To
Woodrow Wilson House
(Henry Parker Fairbanks House)
2340 South S Street, N.W.
Washington
District of Columbia

HABS No. DC-133

Jack E. Boucher, Photographer June 1964

DC-133-1	PERSPECTIVE VIEW OF MAIN ELEVATION
DC-133-2	MAIN ELEVATION, DETAIL OF DOORWAY
DC-133-3	REAR ELEVATION
DC-133-4	FIRST FLOOR, ENTRANCE HALL
DC-133-5	MEZZANINE LEVEL, STAIR HALL
DC-133-6	SECOND FLOOR, LIBRARY, VIEW TOWARD FIREPLACE
DC-133-7	SECOND FLOOR, FORMAL DINING ROOM
DC-133-8	SECOND FLOOR, FORMAL DINING ROOM, VIEW OF FIREPLACE
DC-133-9	SECOND FLOOR, DRAWING ROOM
DC-133-10	THIRD FLOOR, STAIRWAY, VIEW OF ARCHED WINDOW
DC-133-11	THIRD FLOOR, BEDROOM

HABS
DC,
WASH,
220-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum to:

Woodrow Wilson House
(Henry Parker Fairbanks House)
2340 S Street NW
Washington
District of Columbia

HABS No. DC-133

Photographs DC-133-1 to DG-133-11 were previously transmitted to the Library of Congress

Louise T. Taft, Photographer, August 1985.

- DC-133-12 OBLIQUE VIEW OF NORTH FACADE FROM SOUTHWEST
- DC-133-13 DETAIL OF FRONT ENTRANCE WITH DRAWING ROOM WINDOW ABOVE
- DC-133-14 WALL FACING DECATUR PLACE AT SOUTH EDGE OF PROPERTY, FROM SOUTHEAST
- DC-133-15 OBLIQUE VIEW OF WALL FACING DECATUR PLACE, FROM WEST
- DC-133-16 DETAIL OF GATE IN WALL FACING DECATUR PLACE
- DC-133-17 TERRACED GARDEN FROM SECOND FLOOR PORCH, LOOKING SOUTH TOWARDS DECATUR PLACE
- DC-133-18 DETAIL OF (CLOSED) DRIVEWAY GATES LOOKING NORTH FROM DRIVEWAY
- DC-133-19 PRIVATE SIDE ENTRANCE ADDED IN 1921 TO GIVE BARRIER-FREE ACCESS FROM THE DRIVEWAY TO THE ELEVATOR.
[Wrought iron railings, extended upper step of stoop (indicated by the darker concrete between the two vertical posts), and wooden ramp added by the National Trust to meet modern barrier-free access codes, circa 1980.]
- DC-133-20 WINE CELLAR
[This is the lowest room in the house, under the service entrance from S Street. Note reinforced concrete floor slab above (reinforced concrete floor slabs were used throughout the house).]
- DC-133-21 ICE BOX ON WEST WALL OF KITCHEN, FIRST FLOOR
- DC-133-22 STOVE ON WEST WALL OF KITCHEN, FIRST FLOOR
- DC-133-23 GLASS FRONTED CHINA CABINET ON EAST WALL OF KITCHEN, FIRST FLOOR

- DC-133-24 VIEW INTO SOLARIUM FROM UPPER TERRACE OF GARDEN
[Note the curved doors.]
- DC-133-25 VIEW FROM MAIN HALL THROUGH INTERIOR WINDOW TO SOLARIUM
[Note how much light enters this interior space from the solarium. The hall also receives light from the lightwell window of the main stairs to the third floor, out of sight to the left.]
- DC-133-26 SERVING KITCHEN, SECOND FLOOR, SHOWING GLASS FRONTED CHINA CABINETS AND MONEL METAL SINK.
- DC-133-27 THIRD FLOOR MAIN HALL FROM SIDE HALL LEADING TO SERVICE STAIRS
[This hall is lit by three natural sources, the lightwell window of the main stairs visible in the distance, the skylight in the linen closet at the extreme left, and from the glazed openings in the interior and exterior doors of the nurse's room, out of sight to the right.]
- DC-133-28 LINEN CLOSET ON THIRD FLOOR, SHOWING GLAZED OPENINGS WHICH GIVE LIGHT TO THE MAIN HALL
[Photograph DC-133-27 was taken from the arched opening to the left.]
- DC-133-29 DETAIL OF SKYLIGHT IN LINEN CLOSET, THIRD FLOOR
[The skylight is on the north roof, outside the laundry.]
- DC-133-30 GAS FIRED CLOTHES DRYER IN LAUNDRY, FOURTH FLOOR
[No longer functioning; used for storage.]
- DC-133-31 DETAIL OF CONTROLS, ELECTRIC MOTOR, AND LOWER SHEAVES OF OTIS PASSENGER ELEVATOR ADDED IN 1921, BASEMENT.
[The original equipment, shown here, operated on direct current from the Massachusetts Avenue trolley line, abandoned in 1961.]
- DC-133-32 DETAIL OF ORIGINAL OTIS ELEVATOR COMPANY MOTOR, BASEMENT
- DC-133-33 DETAIL OF LOWER ELEVATOR SHEAVES, BASEMENT
- DC-133-34 DETAIL OF SHEAVES AT BASE OF ELEVATOR SHAFT, LOWER LIMIT SWITCH AND SHOCK ABSORBERS, BASEMENT
- DC-133-35 DETAIL OF DOOR TO ELEVATOR AND CAB CATE, FIRST FLOOR
- DC-133-36 DETAIL OF UPPER PART OF ELEVATOR CAB, SHOWING BOTH CAB GATES
[The elevator opened to the west on the first and second floors and to the north on the third floor.]
- DC-133-37 DETAIL OF UPPER ELEVATOR SHEAVES AND TOP OF ELEVATOR SHAFT, FOURTH FLOOR

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
DC,
WASH,
220

ADDENDUM TO
WOODROW WILSON HOUSE
(HENRY PARKER FAIRBANKS HOUSE)
2340 S Street, NW
Washington
District of Columbia

HABS No. DC-133

DC-133-1 through DC-133-37 were transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Walter Smalling, Photographer

DC-133-38 (CT) VIEW OF NORTH FACADE